

Information Bulletin No. IB07-004

May 11, 2007

ALERT

**Jordair Coalescer Filter Canister on
Model K401 Air Compressor**

During an incident investigation, it has been found that some Jordair coalescer filter canisters on the Model K401 Air Compressor could be over-stressed in cyclic service. Pressure equipment in cyclic service can result in metal fatigue. In this case, failure could occur through cracking on the threads of the canister. When that occurs, this can have disastrous results when the system is under pressure.

These compressors are typically utilized in filling Self Contained Breathing Apparatus (SCBA). If you have this model of air compressor in your plant, you are advised to contact the manufacturer at www.jordair.ca and request Doc. Jordair Safety Warning Filters Rev. #2 Feb. 06, 2003.

K. T. Lau, Ph.D., P.Eng.
Chief Inspector and Administrator
Pressure Equipment
Province of Alberta