

Information Bulletin No. IB11-014

August 9, 2011

ALERT

**McDonnell & Miller Model 150S Control
MANUAL RESET Arm Binding**

We have been made aware of a potential issue with the McDonnell & Miller Model 150S low water fuel cutoff **manual reset** control arm. Detailed information regarding this issue may be accessed at:

http://www.doli.state.mn.us/ccld/PDF/ID11_reset.pdf.

The referenced document explains how the reset mechanism works, how to verify operation and what could occur if the reset mechanism binds.

Owners of boilers are responsible to ensure controlling devices on them are maintained in good working order. If your boiler is equipped with this type of low water fuel cutoff control, you should ensure the device is examined by a competent person and in accordance with the instructions contained in the above referenced document.

For more information regarding this issue please contact:

Mr. Greg Roder
McDonnell & Miller
8200 North Austin Avenue
Morton Grove IL 60053
Telephone: (847) 983-5714

The number of affected units in Alberta is unknown and we have not been notified of any incidents regarding these units.

For more information on pressure equipment safety in general, visit our web site at www.absa.ca

<original signed by>

Mike Poehlmann
Acting Administrator and Chief Inspector
Pressure Equipment Safety
Province of Alberta