



November 1999

ALERT

Honeywell recalls Fluid Power Actuators Model V4055/V4062/V9055 with date codes 9744 through 9841

We have been advised by Honeywell that V4055, V4062 and V9055 Fluid Power Actuators with manufacturing date codes of 9744 through 9841 may have a manufacturing defect which can cause a safety issue. Honeywell is notifying customers of the recall. Honeywell provides an information letter detailing the possible hazards together with a list of "Frequently Asked Questions and Answers". If you believe that you may have these actuators, please contact the supplier concerned or Honeywell direct through their toll free number at 1-800-587-7532.

This information is provided in our web-site to allow for improved pressure equipment safety. We appreciate being advised by Honeywell in this instance. We also urge all pressure equipment manufacturers to provide us with information whenever and wherever pressure equipment safety may be impacted upon.