

PRODUCT RECALL BULLETIN**05/06/2014****UTD30L, UTD30LA, UTD30H, UTD30HA (TI-P154-01)****CRN 0E07003.2****Background/Product Issue:**

Spirax Sarco Canada Ltd has notified ABSA that there are design issues with the above noted equipment model numbers, which affect the ability of the equipment to safely retain pressure. Please be advised that the above noted model numbers risk leakage and failure when under pressure and at high temperatures, due to the retaining ring associated with this design.

This product has been widely in use for many years without any catastrophic incidents occurring whatsoever. That said, and notwithstanding that there is no historic evidence of this product leaking in service as a result of this failure, as part of our commitment to product quality and to our customer's safety, we wish to inform our customers of this issue.

Action Required:

Per Section 40(4) of the Alberta Safety Codes Act, this design has been de-registered and the above noted model numbers should be withdrawn from use.

Please contact your local Spirax Sarco service agent for further advice referencing this bulletin.