

Information Bulletin No. IB13-010

July 31, 2013

ALERT

ABSA has been made aware that Hansen Pressure Relief Valves (PRVs) Cat. Nos. H5600A, H5601, H5602, H5600R, H5602R and H5632R, S.Nos 02B11 through 04B13 may be susceptible to internal corrosion when exposed to standing water inside the valve. We are given the understanding that the risk may be remote, but the failure of a pressure relief valve could conceivably result in serious personal injury and/or property damage. The valves were sold for industrial use between February 16, 2011 and April 4, 2013.

The supplier issued an 'Urgent Product Safety Notice' on June 21, 2013 in this regard. The notice may be accessed at Hansen's web site at <http://www.hantech.com/notifications/PRVPublicNotice.pdf>.

Those owners who may have the above PRVs installed on the pressure equipment are asked to review the notice posted at Hansen's website, contact Hansen for further information and take immediate action replacing valves as recommended by Hansen.

<original signed by>

K. T. Lau, Ph.D., P.Eng.
Administrator, Province of Alberta Pressure Equipment Safety
Chief Inspector, ABSA the pressure equipment safety authority